

# STOFFER MED VELDIG HØY BEKYMNING (SVHC) INFORMASJON OM TRYGG BRUK

## REACH-ARTIKKEL 33-INFORMASJON OM STOFFER MED VELDIG HØY BEKYMNING (SVHC - SUBSTANCES OF VERY HIGH CONCERN)

Kjære kunde,

REACH-reglene (reg. EC 1907/2006) artikkel 33 (1) har til hensikt å la kunder av leverte produkter ta relevante risiko-forhåndsregler som følge av tilstedeværelse av produkter med stoffer med veldig høy bekymring (SVHC-er) listet opp i den nåværende kandidatlisten til autorisasjon, for å sikre trygg bruk.

FORDstøtter de underliggende målene til REACH generelt og artikkel 33(1) spesielt. Den stemmer overens med vår selvpålagte forpliktelse til å fremme ansvarlig produksjon, håndtering og bruk av våre produkter.

### Identifisering av SVHC-er

Så langt vi kjenner til, basert på informasjon mottatt fra vår leveringskjede og vår egen produksjonsinformasjon, er SVHC-er tilstede i komponentprodukter med mer enn 0,1 % w/w vist på den relevante "SVHC-listen" for det/den spesifikke kjøretøyet/delen.

### Spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er

Hvis aktuelt er spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er lagt til ved den relevante "SVHC-listen" for det/den spesifikke kjøretøyet/delen.

### Generell informasjon om trygg bruk av produkter

Hvert FORD-kjøretøy er utstyrt med en eierhåndbok, som inkluderer informasjon om trygg bruk for eieren/brukeren av kjøretøyet. FORDs informasjon om reparasjon og service av kjøretøy og originale deler inkluderer også informasjon om trygg bruk for service-medarbeidere.

Når det er tilstede i deler av dette kjøretøyet vil SVHC-er vist i den relevante "SVCH-listen" for det/den spesifikke kjøretøyet/delen være inkorporert på en slik måte at potensiell eksponering for kunder er minimert, og fare ovenfor mennesker og miljø kan ekskluderes så lenge kjøretøyet og dets deler brukes som tiltenkt, og enhver reparasjon, service og vedlikehold blir utført i henhold til tekniske instruksjoner for slike aktiviteter, industristandarder og god praksis.

Et kjøretøy som skal vrakes kan kun leveres lovlig innen EU til et autorisert behandlingsanlegg (Authorised Treatment Facility - ATF). Kjøretøydeler skal kun avhendes i henhold til gjeldende lokale lover og etter veiledning fra lokale myndigheter.

# Modell: Ford Puma

SVHC-liste basert på ECHA-kandidatliste fra 1. juli 2023

Spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er

Ingen spesifikk informasjon om trygg bruk er nødvendig - følg generell informasjon om trygg bruk av produkter.

| Commodity  | REACH SVHCs   |
|--|---|
| A/C Compressor   | Lead [7439-92-1]  |
| A/C Lines, Receiver Drier and Accumulator              | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]<br>Lead [7439-92-1]                        |
| ABS/ESC Module   | Lead [7439-92-1]  |
| Accessories  | 1,2-Dimethoxyethane [110-71-4]<br>Lead [7439-92-1]  |
| Active and Air Suspension                              | Lead [7439-92-1]  |
| Adaptive Cruise Control                                | Lead [7439-92-1]  |
| Air Brakes   | Lead [7439-92-1]  |
| AIS - Air Cleaner and Low Pressure Ducts               | TBBA [79-94-7]  |
| AIS - High Pressure Ducts                              | Lead [7439-92-1]  |
| Alternator   | Diboron-trioxide [1303-86-2]  |
| Antenna  | Lead [7439-92-1]  |
| Audio and Navigation Head Units                        | Lead [7439-92-1]  |
| Battery  | Lead [7439-92-1]  |
| Body Structure - Decklid/Liftgate (incl Hinge/Supt)    | Lead [7439-92-1]  |
| Body Structure - Floor Pan - Front Floor and Side Sill | Diboron-trioxide [1303-86-2]<br>Octamethylcyclotetrasiloxane [556-67-2]                                     |
| Body Structure - Floor Pan - Rear Floor                | Dicyclohexyl-phthalate [84-61-7]<br>Lead [7439-92-1]  |
| Brake - Parking  | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]<br>Lead [7439-92-1]<br>Methyloxirane [75-56-9] |
| Brake Actuation  | Lead [7439-92-1]<br>TBBA [79-94-7]  |
| Brake Tubes and Hoses                                  | Lead [7439-92-1]  |
| Brakes - Caliper & Anchor Brkt Assy (Front, Rear)      | Lead [7439-92-1]  |
| Bulk Materials (PMT100)                                | C,C'-azodi(formamide) [123-77-3]<br>Dicyclohexyl-phthalate [84-61-7]  |
| Bumpers Beams (Un-Exposed) - Front/Rear                | Lead [7439-92-1]  |
| Camshaft and Drive                                     | Lead [7439-92-1]  |
| CHMSL  | Lead [7439-92-1]  |
| Clutch / DMF (Dual Mass Flywheel)                      | Lead [7439-92-1]  |

|   |  |
|---|--|
| Console Floor/Rear                                  | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]      |
| Control Arm and Bushing Assembly                    | Imidazolidine-2-thione [96-45-7]                             |
| Cooling Fans  | Lead [7439-92-1]   |
| Cooling Hoses & Bottles                             | Lead [7439-92-1]   |
| EDS Wiring Assembly & Components                    | Lead [7439-92-1]   |
| EGR System (Gas/Diesel)                             | Lead [7439-92-1]   |
| Electro/Mechanical Devices                          | Lead [7439-92-1]   |
| Electronic Control Panel and CCH                    | Lead [7439-92-1]   |
|   | N,N-Dimethylacetamide [127-19-5]                             |
|   | Octamethylcyclotetrasiloxane [556-67-2]                      |
| Electronic Modules - Amplifiers                     | Lead [7439-92-1]   |
| Electronic Modules - Displays                       | 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1] |
|   | Lead [7439-92-1]   |
| Electronic Modules - Door Zone                      | Lead [7439-92-1]   |
| Electronic Modules - Headlamp                       | Lead [7439-92-1]   |
| Electronic Modules - Power Decklid/Liftgate (PLG)   | Lead [7439-92-1]   |
| Electronic Modules - Suspension                     | Lead [7439-92-1]   |
| Electronic Modules - SYNC                           | 2-Methylimidazole [693-98-1]                                 |
|   | Lead [7439-92-1]   |
| Engine Covers and Badges                            | Lead [7439-92-1]   |
| Engine Oil Pumps and Coolers                        | Bis(4-chlorophenyl) sulfon [80-07-9]                         |
| Engine Sealing (Including head gaskets)             | Lead [7439-92-1]   |
| Engine Water Pumps                                  | Lead [7439-92-1]   |
| Evaporator and Blower Assembly (HVAC Module)        | Lead [7439-92-1]   |
| Exhaust Cold End (Muffler & Output Pipe Assembly)   | Lead [7439-92-1]   |
| FEAD  | Lead [7439-92-1]   |
| Fuel Canister Assembly                              | Lead [7439-92-1]   |
| Fuel Lines  | Lead [7439-92-1]   |
| Fuel Tanks  | Lead [7439-92-1]   |
| Gas Engine Ignition                                 | Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7]    |
| Glass And Channel Assy - Front/Rear                 | TBBA [79-94-7]   |
| GOR and Radiator Support                            | Lead [7439-92-1]   |
| Half Shaft(s)                                       | Lead [7439-92-1]   |
|   | Sodium borate, decahydrate [1303-96-4]                       |
| Headlamp / Side Marker                              | Lead [7439-92-1]   |
|   | TBBA [79-94-7]   |
| Headliner / Sunvisor                                | C,C'-azodi(formamide) [123-77-3]                             |
| Heat/Sound Insulators - Dash/Tunnel/Wheelhouse/Hood | Melamine [108-78-1]  |
| I/S Mirror  | Lead [7439-92-1]   |
| Instrument Cluster                                  | Lead [7439-92-1]   |
|   | Octamethylcyclotetrasiloxane [556-67-2]                      |
| Interior Lighting                                   | 1,2-Dimethoxyethane [110-71-4]                               |
|   | Lead [7439-92-1]   |
|   | TBBA [79-94-7]   |
| IP Finish Panels/Registers                          | C,C'-azodi(formamide) [123-77-3]                             |
| Latches - Hood, Decklid and Liftgate Latches        | Lead [7439-92-1]   |
|   | TBBA [79-94-7]   |
| Latches - Side Door/Latch Mini Module               | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]      |

|   |  |
|---|--|
| Locks                                   | Lead [7439-92-1]   |
|   | TBBA [79-94-7]   |
| Lubrication                             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]                      |
|   | Lead [7439-92-1]   |
| Mirrors                                 | Lead [7439-92-1]   |
| Moonroof                                | Lead [7439-92-1]   |
| Overhead Console                        | Lead [7439-92-1]   |
| Park Assist                             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]        |
|   | Lead [7439-92-1]   |
|   | TBBA [79-94-7]   |
| PATS Transceiver                        | Lead [7439-92-1]   |
| PCV System                              | Imidazolidine-2-thione [96-45-7]   |
|   | Lead [7439-92-1]   |
| Pedal Box                               | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]                      |
| Pistons and Con Rods                    | 1-Methyl-2-pyrrolidone [872-50-4]  |
| Plastic Bumpers and Fascias             | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]        |
|   | Lead [7439-92-1]   |
|   | TBBA [79-94-7]   |
| Powertrain Control Module (PCM/EEC/ECM) | Lead [7439-92-1]   |
| PT Mounts                               | Lead [7439-92-1]   |
| PT Sensors                              | 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9]              |
|   | Lead [7439-92-1]   |
| Rain and Daylight Sensor                | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9] |
| Restraint Electronics                   | Lead [7439-92-1]   |
| Seat Belts (Front and Rear)             | Disodium-octaborate [12008-41-2]   |
|   | Lead [7439-92-1]   |
| Seats - Foam - Cut and Sew              | Lead [7439-92-1]   |
| Seats - JIT                             | Lead [7439-92-1]   |
| Seats - Structures                      | 1-Methyl-2-pyrrolidone [872-50-4]  |
|   | Lead [7439-92-1]   |
|   | TBBA [79-94-7]   |
| Shifter Cables/Brackets - Auto          | 1-Methyl-2-pyrrolidone [872-50-4]  |
|   | C,C'-azodi(formamide) [123-77-3]   |
|   | Lead [7439-92-1]   |
| Shifter Cables/Brackets - Manual        | Lead [7439-92-1]   |
| Side and Rear Vision (BLIS)             | Lead [7439-92-1]   |
|   | Octamethylcyclotetrasiloxane [556-67-2]                                      |
| Smart Data Link Module                  | Lead [7439-92-1]   |
|   | TBBA [79-94-7]   |
| Speakers / Tweeters                     | Melamine [108-78-1]  |
|   | N,N-Dimethylacetamide [127-19-5]   |
| Steering Column                         | Lead [7439-92-1]   |
| Steering Gear and Linkage               | Imidazolidine-2-thione [96-45-7]   |
|   | Lead [7439-92-1]   |
| Steering Wheel, Drive Air Bag           | Alkanes, C14-17, chloro [85535-85-9]   |
|   | Lead [7439-92-1]   |
| Suspension Link Components              | Lead [7439-92-1]   |
| Switches - General Use                  | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]        |
|   | Lead [7439-92-1]   |

|   |   |
|---|---|
| Switches - Headlamp. Window & Door              | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
|   | 4,4'-Isopropylidenediphenol [80-05-7]                                 |
|   | Lead [7439-92-1]  |
|   | TBBA [79-94-7]  |
| Switches - Steering Column                      | 4,4'-Isopropylidenediphenol [80-05-7]                                 |
|   | Lead [7439-92-1]  |
| Taillamp / Redundant                            | Lead [7439-92-1]  |
| Temperature Sensors - Climate                   | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
|   | Hexahydromethylphthalic-anhydride [25550-51-0]                        |
|   | Lead [7439-92-1]  |
|   | TBBA [79-94-7]  |
| Throttle Bodies                                 | Lead [7439-92-1]  |
| Tires   | Lead [7439-92-1]  |
| TMK and Tools                                   | Lead [7439-92-1]  |
| TPMS  | 1,3-Propanesultone [1120-71-4]  |
|   | Decamethylcyclopentasiloxane [541-02-6]                               |
| Transmission - Auto                             | Lead [7439-92-1]  |
| Transmission - Manual                           | Lead [7439-92-1]  |
| Transmission (Auto) - External Fluid Components | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
| Transmission (Auto) - Large Al Die Casting      | Lead [7439-92-1]  |
| Transmission (Auto) - Oil Pumps                 | Nonylphenol [25154-52-3]  |
| Transmission (Auto) - Solenoids & Sensors       | Lead [7439-92-1]  |
| Turbocharger                                    | Lead [7439-92-1]  |
| Window Regulator                                | Lead [7439-92-1]  |
| Wiper Assembly (Rear, Front) & Washer System    | Lead [7439-92-1]  |
| xEV - DCDC                                      | Diboron-trioxide [1303-86-2]  |
|   | Lead [7439-92-1]  |
| xEV - eDrive                                    | Nonylphenol [25154-52-3]  |
| xEV - Traction Battery (as Shipped)             | Lead [7439-92-1]  |
| xEV - Traction Battery Charging                 | Lead [7439-92-1]  |